

MONUMENT RECORD

Corner I.D. #

Q-10


STATE OF INDIANA - COUNTY OF MONROE

Section Fifteen (15), Township 9 North, Range 1 East


Monument Description & Remarks: Stone w/"X" found at the SE corner of
NE 1/4 of NE 1/4 of section. Stone leans west. Corner witnessed 8/17/88.
See attached notes.

Recovery Tie Drawing

Galvanized nail
in base, 2"
Sassafras




Stone w/"X"
found



Galvanized nail
in base, 12"
Tulip Poplar



Galvanized nail in
base, 12" Shagbark
Hickory



● At Corner



Not To Scale

State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 8th day of February, 1995 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Morgan-Monroe State Forest

United States Government Agency

Darrell Breedlove, Timber Specialist

Title

Field Book:

n/a

Page:

n/a

SECTION 15, T 9 N, R 1 E

1. On July 18, 1983, boundary line location and marking was completed for the NE $\frac{1}{4}$, NE $\frac{1}{4}$, SEC 15. The line was painted on the state side with orange tree marking paint, and signs were posted at all corners except SW, where an encroachment problem may exist (report made). The following corner markers were found: SE-stone (needs to be witnessed), ~~NE pipe~~, ~~NW pipe~~. No corner marker or other clear evidence was found to establish the SW corner.

Darrell Breedlove

Darrell Breedlove, Timber Specialist

- 2a. On May 30, 1988, the NE corner stone of sec.15 was witnessed as follows:

<u>Az</u>	<u>Species</u>	<u>DBH(in.)</u>	<u>Distance (Ft.)</u>
094	Sugar Maple	12	20.0
194	Tulip Poplar	12	14.2
342	Am. Beech	21	27.5

Pk nails were driven at the base of witness trees. This stone has an "X", and it leans west.

An erroneous 1 in. pipe, set in concrete with a steel fence post next to it, is Az 038 and 37.0 ft. from the stone.

- b. On August 17, 1988, a fence post was driven next to the NE corner stone of Sec. 15.

Darrell Breedlove

Darrell Breedlove,

Timber Specialist

3. On August 17, 1988, the SE corner, NE $\frac{1}{4}$, NE $\frac{1}{4}$, Sec.15, T9N, R1E was witnessed as follows:

<u>Az</u>	<u>Species</u>	<u>DBH (in.)</u>	<u>Distance (Ft.)</u>	<u>Comments</u>
232	Tulip Poplar	12	13.5	Hollow S 52° W ✓
120	Shagbark Hickory	12	18.0	S 60° E ✓
017	Sassafras	2	10.2	W/plastic sign N 17° E ✓

Galvanized nails were driven at the base of witness trees. This stone has an "X" and it leans

west. It is bearing S1.6° E (1° W declin.) from a stone found at the NE corner, Sec. 15.

Darrell Breedlove

Darrell Breedlove

Timber Specialist